

HMMWV MISHAP CLAIMS ONE SOLDIER'S LIFE

A National Training Center Operations Group, Fort Irwin, California, Soldier was killed in a HMMWV mishap that occurred on 2 June 2015 at approximately 1330 local on Fort Irwin. The 37-year-old SFC was involved in a one-vehicle accident that caused the HMMWV to rollover. The Soldier was driving the M1097 HMMWV as the sole occupant when he overturned on an unimproved roadway. The Soldier was determined not to have been wearing his seatbelt and he was pinned by the right front passenger's side tire. The Soldier died as a result of the accident. A Centralized Accident Investigation (CAI) team from the US Army Combat Readiness Center is investigating. [News Article](#)

This is the [4th](#) Class A **AMV** (Army Motor Vehicle) fatality in FY15 compared to **4** for the same time frame in FY14. This PLR does not identify specific root causes of this incident as the investigation is ongoing. Further details will be available at a later date on RMIS (RMIS Login Required).

Our Army depends on you to use these PLRs to help Soldiers understand the impact of decisions made on and off duty.

The [U.S. ARMY COMBAT READINESS CENTER](#) is interested in your comments; please [click here](#) to provide feedback on the Preliminary Loss Reports (PLR). [FAQs](#) and additional resources can be found on the USACRC website at <https://safety.army.mil>

